


***UNOSAT Damage Assessment of  
Great Mosque of Al Nuri  
Mosul, Nineveh Governorate, Iraq***



22 June 2017

# Great Mosque of Al Nuri Damage Assessment

19 June 2017



*Imagery Copyright: Airbus Defense and Space Image*

Image analysis: UNITAR-UNOSAT  
Copyright: DigitalGlobe 2017

# Great Mosque of Al Nuri Damage Assessment

22 June 2017



Image analysis: UNITAR-UNOSAT  
Copyright: DigitalGlobe 2017

# Great Mosque of Al Nuri Damage Assessment

22 June 2017

Section of the mosque complex where the minaret used to be located.

The entrance to the mosque has sustained severe damage.

Image analysis: UNITAR-UNOSAT  
Copyright: DigitalGlobe 2017

UNITAR Operational Satellite Application Programme (UNOSAT)

Contact information:

[www.unitar.org/unosat](http://www.unitar.org/unosat)

[unosat@unitar.org](mailto:unosat@unitar.org)

T +41 22 767 4020



**unitar**

United Nations Institute for Training and Research

United Nations Institute for Training and Research

Institut des Nations Unies pour la Formation et la Recherche

Instituto de las Naciones Unidas para Formación Profesional e Investigaciones

Учебный и научно-исследовательский институт

Организации Объединенных Наций

معهد الأمم المتحدة للتدريب والبحث

联合国训练研究所

Palais des Nations

1211 Geneva 10

Switzerland

T +41 22 917 8400

F +41 22 917 8047

[www.unitar.org](http://www.unitar.org)